Specifications:

Range: -58° to 446°F or -50° to 230°C

Resolution: 0.1°F or C Full Range

Battery: 2032 (included)

Auto Shut-Off: After 5 minutes if no change in temperature unless feature is set to 'DISABLE'

Response Time: I second

Auto Shut-Off Feature:

This thermometer has been designed to allow a user to 'DISABLE' and 'ENABLE' the Auto Shut-Off feature. To change between settings press and hold the 'On/Off' buttor for 3 seconds until either 'DISABLE' or 'ENABLE' is displayed on the LCD. After thermometer is turned off it will

Caution

Do Not leave thermometer in oven while cooking.

recall the last setting unless the battery is removed.

General Operation:

- Press 0n / Off button to turn on.
- Press F/C button to select temperature scale
- probe at least 1" into foo being tested.

3. Insert stainless steel

- Leave probe in food until display stabilizes.
- Press HOLD button to lock temperature reading.
- Remove probe from food and press HOLD button again to release reading.
- Clean by hand. Do Not completly immerse thermometer in water.